Qty:

Date

Monday, 05/05/2008 4:12:26 PM

Úser:

Julie Lecocq

**Process Sheet** 

Customer

: CU-DAR001 Dart Helicopters Services

Job Number **Estimate Number**  : 39059

P.O. Number

: 10346

This Issue

Prsht Rev.

First Issue

**Previous Run** 

: 05/05/2008

: NC

: // : 38951

Type

S.O. No. :

: SKIDTUBES

Part Number

**Drawing Name** 

: D2596 - D2596 REV D

**Drawing Number** 

**Project Number** 

: D **Drawing Revision** 

Material **Due Date** 

: 10/05/2008

: N/A

: 205 SKIDTUBE "I" BEAM

4 Um:

Each

Written By

Checked & Approved By

Comment

: Est: D 99.02.02

Changed QA to QC, Added Step 6 and Cost D

Est Rev:E 07-07-09 Incorperated DEO 9183 JLM

**Additional Product** 

Job Number:



Seq. #:

**Machine Or Operation:** 

Description:

1.0

D25003100

Ext'n - I' Beam Web 4"

Comment: Qtv.:

1.0000 Each(s)/Unit

Total: 4.0000 Each(s)

Extrusion "I" Beam Web 4"

Pick:

Qty

Part Number D2500-3-100

Description Extrusion

N 35-7


. 2.0


SKIDTUBES 1

SKIDTUBESS RESOURCE 1









3- Open to 0.630" diameter as per Dwg D2596

4- Deburr

3.0

HAND FINISHING

HAND FINISHING RESOURCE #1



Comment: HAND FINISHING RESOURCE #1

Acid Etch and Alodine per QSI 005 4.1

W 8-5-7



. 1

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

## **Dart Aerospace Ltd**

W/O:		WORK ORDER CHANGES						
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
	-							
							•	
Dart No		DAD #1 Foult Cotomony	NCD: Voc	No DO	١.	Data		

Part No:	PAR #: Fault Category:	NCR: Yes No DQA: Date:
		QA: N/C Closed: Date:
NCR:	WORK ORDER NON-C	ONFORMANCE (NCR)

NCR:		WORK ORDER NON-CONFORMANCE (NCR)								
DATE		Description of NC Section A	Corrective Action Section B			Verification	Ammrayal	Annroyal		
	STEP		Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector		

NOTE: Date & initial all entries

Date:

Monday, 05/05/2008 4:12:26 PM

User:

Julie Lecocq

**Process Sheet** 

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: 205 SKIDTUBE "I" BEAM

Job Number: 39059

Part Number: D2596

Job Number:



Seq. #:

**Machine Or Operation:** 

Description:

5.0

PACKAGING 1

PACKAGING RESOURCE #1

Comment: PACKAGING RESOURCE #1

Identify and Stock Location: L.G. 8-5-7

6.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE


Job Completion



mx

Dart Ae	rospace	Ltd	·	•					
W/O:			W	ORK ORDER CHANGES	3				
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву			Approval Chief Eng / Prod Mgr	Approval QC Inspector
									,
			33.						
D4 M -	_						_	i i i i i i i i i i i i i i i i i i i	<u> </u>
Part No	: <u></u>	PAR #:	Fault Cate	gory:				-	
	•				QA: N	I/C Close	d:	_ Date: _	
NCR:			WORK ORD	ER NON-CONFORMAN	CE (NCF	₹)	-		ger ja
DATE	STEP	Description of NC		Corrective Action Section B		Verification		Approval	Approval
DATE		Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Secti	Section C	Chief Eng	QC Inspector
						-			
							•		7.7

NOTE: Date & initial all entries



y ses W. ٠.